

Mini GAC & Mini GAC plus quick user guide



SWITCH ON



SELECT GRAIN, PRESS ENTER



PRESS ENTER FOR EMPTY CELL TEST



FILL LOADER



PLACE LOADER ON TOP AND OPEN



LEVEL OFF GRAIN



PRESS ENTER



RESULTS ARE DISPLAYED